

WA3019

18A

8/29/02

Joan Beth
Rue Ann
Shawn
Lina
Jennifer
Cheryl
Kend

Proposed Agenda

**USEPA Region 10 & J. H. Baxter & Co.
Arlington, WA Facility
Thursday, August 29, 2002 at 1:00 p.m.**

- Introductions
- Overview of Current Work at the Facility
- Implementation of Site Investigation
- NPDES Permit Update
- Other Activities
- Characterization of Stormwater at the Facility
- Impact of Characterization on Costs vs. Impact on Discharge Criteria
- Regulatory Issues
- Other Regulatory Issues

Shawn - lower level presentation
Les out. Hurt back.

Sept 9th deep wells

Data starting to arrive in ~ Sept 9
Deep hole starting about Sept 15

BWSF owns ditch along RR. City has easement (which originally was JH Baxter). City agreeable to NPDES but they have no control of it.

Storm water treatment, data will be in with Sept 15 progress report
Alum drops opacity quickly
Capacity 2 million. Data should be in soon.

Permits and design in process. WDOE & City will review in parallel
Grading and stormwater design to WDOE/EPA/city 10/15/02
Construction in spring 2003

Ditch has been studied. Hydrologic Investigation Study
Shapiro will review and decide if additional data is needed.
Already working on data. Shapiro had done some of original ditch study.

FILE COPY



ERI will do plant design. Have remediation experience.

Geoprobe did not work. Hard formation.

Sarah Beth

Jones of letter to AWP I on hazardous waste -
"Listed hazardous waste" issue. Cost is much greater.

Construction, Treatment is not the issue - that will be done.

Need to get out of listed

Need to work with WDOE

JMS - It is material on ground first.

Cheryl Can use lined ditches?

JMS WDOE has authority for closure.

Shawn Sitch as impoundment? Permits? Double pipe needed?

Kim If media does not come in contact

Shawn - confused ---

JBW - If precipitation falls on haz waste

JMS Separate from

Ruehan Remedy aprons to avoid contact. Treat as

JMS part of treatment facilities,
Cleaning up is "closure"

Shawn Second piece is hard pipe to ditch.

JMS Water on apron. Coopy with drip collection plan.

Shawn Past oil spills of other such which would come

JMS into contact with

Distinction about areas where precipitation would fall.

Treatment area, spills area aprons, treated pole storage.

Seemed deal to all.

Shawn Points of compliance issues for after data

JH/Baxter Meeting (cont) ②

29 Aug 2007

JKW How can we prove that drainage has been controlled
Cheryl State is now authorized for RCRA Subpart W. EPA
started because the state did not have authority.
Need to go back and review NOV letter.

Rue Ann
+ Shawn

How does picking up drips on concrete aprons
get documented? Cleared x by y inches of
floor using soap and x absorbent pads.
AAPI does not offer audits for "compliance assistance"